SFUND RECORDS CTR 0816-90175 e 9/18/86

Preparer's Name Ronald H. Clawson

		SOURCE	INFORMATION
1.	Site ID Number		AR0007
2.	Site Mame	RWQCB File	Jasco Chemical Co., Villa Street
3.	Site Location	RWQCB File	1710 Villa St. Mountain View, CA
4.	County	RWQCB File	Santa Clara
5.	Owner (Address & telephone no.)	RWQCB File	Jasco Chemical Corporation 1710 Villa St. Mountain View, CA 94042 (415) 968-6005
6	Operator (Address & telephone no.)	9/17/86 telephone conversation with Ronald Clawson	Jasco Chemical Corporation 1710 Villa St. Mountain View, CA 94042 (415) 968-6005
7.	Type of Ownership	"	Private
8.	Status	8/1/86 RWQCB File	Active
9.	Source Activity	8/1/86 RWQCB site visit.	Manufacture of paint remover, stains, and other chemical products.
10	Years of Operation	8/1/86 RWQCB File	About 10 years
11.	Facility Type	Jan. 14, 1983 RWQCB spill Incide report. May 15, 1985 Quest Engineering Report	ditch to the rear of the facility.
12.	Waste Type and Description	Jasco Chemical Cor letter dated 8/29/86	Unknown solvent. A monitoring well was installed and soil and groundwater samples were collected. A technical report was due 9/9/86. That report is to include a discussion of the results.

·	
A January 14, 1983 complaint from a private citizen claimed that the facility described solvents at the rear of the buildings on a daily basis. The RWQCB requested Jass Chemical Corp. to install a monitoring well at the alleged spill site to determine if the groundwater is contaminated. ire and Explosion No	
nspections (date, type, by whom, recommendations)	
8/1/86 by Ronald Clawson, RWQCB. This was a general site visit to determine who the Jan. 1983, alleged dumping occurred and to discuss the siting of a purposed groundwater monitoring well with the Jasco Chemical Corporation consultant, Questing engineering Geologist, Patrick Casey.	- 1
	j
None .	
	-
Initial recommendation for further action:	
Initial recommendation for further action: A detailed site investigation may be necessary if the new monitoring well locate adjacent to an area of reported past spillage is contaminated. If contaminated, then the site should also be scored using the Hazard Ranking System.	
A detailed site investigation may be necessary if the new monitoring well locate adjacent to an area of reported past spillage is contaminated. If contaminated, then the site should also be scored using the Hazard Ranking System.	- Fa
A detailed site investigation may be necessary if the new monitoring well locate adjacent to an area of reported past spillage is contaminated. If contaminated, then the site should also be scored using the Hazard Ranking System. EPA recommendation for further action: Active. Dased upon did obtained via phone conversations with Jasco the regional Board be conducting a side investigation. They side investigation show he reviewed for Hazard Ranking scoring. Many Massless info	- Fa
A detailed site investigation may be necessary if the new monitoring well locate adjacent to an area of reported past spillage is contaminated. If contaminated, then the site should also be scored using the Hazard Ranking System. EPA recommendation for further action: Active, based upon did obtained via phone convergations with fasco the regional board be conducting a side investigation. They side investigation show be reviewed for fazzard lanking scoring. Many hastless informations. Response Termination: No Further Action Pending **Active**	- Fa
A detailed site investigation may be necessary if the new monitoring well locate adjacent to an area of reported past spillage is contaminated. If contaminated, then the site should also be scored using the Hazard Ranking System. EPA recommendation for further action: Active. Dased upon did obtained via phone conversations with Jasco the regional Board be conducting a side investigation. They side investigation show he reviewed for Hazard Ranking scoring. Many Massless info	12 usil

A-IX-FORM 890A

12.9-86